

Product Discontinuation Notices

November 4, 2009

Vision Sensors

No. 2009274E

Discontinuation Notice of Strobe Controller. 3Z4S-LT MLEK-C100E1TS

Product Discontinuation

Recommended Replacement



3Z4S-LT MLEK-C100E1TS



3Z4S-LT MLEK-C100E1TS2

Discontinuation date : The end of November, 2009

Caution on recommended replacement

When the customer uses the product to Serial No:1058-00001-00500.
The adjustment of the shutter speed is needed.
The reason for the shutter speed is that the flash luminescence time is different in 1/499 or less.

Difference from discontinued product

Model	Body Color	Dimensions	Wire connection	Mounting Dimensions	Characteristics	Operation ratings	Operation methods
3Z4S-LT MLEK-C100E1TS2	**	*	**	*	*	**	**

** : Fully compatible

* : The change is a little/Almost compatible



-- : Not compatible

- : No corresponding specification

Product Discontinuation and recommended replacement

Product discontinuation	Recommended replacement
3Z4S-LT MLEK-C100E1TS	3Z4S-LT MLEK-C100E1TS2

Dimensions/ Mounting dimensions

Product discontinuation	Recommendable replacement
	

Characteristics

Product discontinuation	Recommendable replacement
<p>Serial No.: 1058-00001 to 00500</p> <p>Strobe flashing time (Range of self adjustment) MAX 2ms (The shutter speed follows to 1/500.)</p> <p>Pulse width : base cycle 10 [μs] / steps 256</p> <p>Serial No. : 1058-00501 to</p> <p>Strobe flashing time (Range of self adjustment) MAX 50ms (The shutter speed follows to 1/20.)</p> <p>Pulse width : base 10 (50,100,200) [μs] / steps 255</p>	<p>Strobe flashing time (Range of self adjustment) MAX 50ms (The shutter speed follows to 1/20.)</p> <p>Pulse width : base 10 (50,100,200) [μs] / steps 255</p>